



### **136 Coolidge Avenue - Contributing**

This is a one- and one-half story side-gabled Craftsman dwelling built ca. 1925. The house has a continuous brick and poured concrete foundation, a roof of asphalt shingles, an interior brick chimney and exterior of aluminum siding. On the main (S) façade is a partial-width, inset porch with square wood posts and a closed wood railing covered with aluminum siding. The main entrance retains its original, three-vertical-light glass and wood door with an aluminum and glass storm door. Windows are original, four-over-one-vertical-light double hung wood sash. On the east façade is a projecting shed roof bay with three, three-over-one-vertical-light double hung wood sash windows. At the roofline of the main façade is a gable roof dormer with a triple set of three-over-one-vertical-light double hung wood sash windows.



At the rear of the dwelling is an original, two-bay, frame garage with original weatherboard siding, a hipped roof of asphalt shingles and two, original, sixteen-wood-panel overhead track doors. At the roofline is a small, hipped roof dormer with paired single-light windows currently boarded over with wood.

**- Contributing**